



INSTITUTE OF INTERNATIONAL CONTAINER LESSORS

**FOR IMMEDIATE RELEASE
May 11, 2007**

Technical Bulletin 004

Briarcliff Manor, New York - IICL President Steven R. Blust., announced today the release of the Institute's Technical Bulletin 004, "Dowel Repair in Container Floors". This technical bulletin outlines a revision to the IICL's Repair Manual for steel freight containers, 5th edition and specifically section 9.3 (dowel repair). The bulletin has been posted online at www.iicl.org and can be accessed by clicking on "Technical Bulletins" on the navigation bar. IICL TB 004 outlines its new criteria for dowel repairs in container floors.

The project was supervised by IICL Technology Committee Chairman, a Luiz Goncalves of Florens Container Services as well as representatives from IICL member companies.

For more information, contact Gary Danback, Director, Technical Services at Tel 1-914-747-9100, Fax 1-914-747-4600 or E-mail gdanback@iicl.org

* * * *

IICL's members are Amficon, CAI, Carlisle, Cronos, Flexi-Van, Florens, GE SeaCO, Gold, Interpool, Textainer, Trac, TAL and Triton.