



IICL Updates

To provide additional clarity on the IICL repair recommendations for bowed downward understructure components, the IICL has released:

- A revised **Technical Bulletin 021 (TB 021)**, applicable to **Dry Van** and **Open Top** containers.
- A new **Flatrack Technical Bulletin 016 (FTB 016)**, applicable to **Flatrack** containers.

Both technical bulletins are available on the IICL website using the links below:

- [Dry Van Technical Bulletins - IICL](#)
- [Flatrack Technical Bulletins - IICL](#)

If you have any questions regarding these technical bulletins, please contact the IICL Technical Department at technical@iicl.org