

January 21, 2022

IICL Technical Bulletin - TB - 024

Title: Amendment to the Repair Manual for Steel Freight Containers, 5th Ed. Forklift Pocket Strap Replacement. Section 8.3.3.1

Reference: Container design has evolved throughout the years including changes to component materials and dimensions, for that reason requiring updates to repair requirements previously published on IICL manuals.

Purpose: Amend the Repair Manual for Steel Freight Containers, 5th Ed., section 8.3.3.1 as follows:

8.3.3.1

"The replacement strap: Measure the inside dimensions between the forklift pocket sides and cut a replacement strap to size. Replacement straps should be at least 6 mm (1/4 in) in thickness and must have the same dimensions as the original component (like for like).

Ensure that the coating type applied to the replacement strap is the same as, or better than, what was present on the original. For example, the top of the strap may have one coating type and the bottom another."

This Technical Bulleting was prepared under the supervision of the IICL Technical Committee.