



INSTITUTE OF INTERNATIONAL CONTAINER LESSORS

Chassis Technical Bulletin CTB 009, 15 July 2009

Title: Major Structural Repairs

Components: Rails, Gussets, Crossmembers, Bolsters and Sub-Frames

Condition: Any bends, bows, dents or damage to rails, gussets, crossmembers, bolsters and sub-frames.

Action Required: No modifications which would include inserts, sections, splices or heat straightening should be made to chassis structural components (rails/gussets/crossmembers/bolsters/sub-frames) without written authorization from the chassis owner.





INSTITUTE OF INTERNATIONAL CONTAINER LESSORS



*1990 M STREET NW, SUITE 650, WASHINGTON, DC 20036-3417 USA
TELEPHONE: 202 223-9800 FAX: 202 223-9810 WEBSITE: www.iicl.org*



INSTITUTE OF INTERNATIONAL CONTAINER LESSORS



*1990 M STREET NW, SUITE 650, WASHINGTON, DC 20036-3417 USA
TELEPHONE: 202 223-9800 FAX: 202 223-9810 WEBSITE: www.iicl.org*



INSTITUTE OF INTERNATIONAL CONTAINER LESSORS



*1990 M STREET NW, SUITE 650, WASHINGTON, DC 20036-3417 USA
TELEPHONE: 202 223-9800 FAX: 202 223-9810 WEBSITE: www.iicl.org*



INSTITUTE OF INTERNATIONAL CONTAINER LESSORS



*1990 M STREET NW, SUITE 650, WASHINGTON, DC 20036-3417 USA
TELEPHONE: 202 223-9800 FAX: 202 223-9810 WEBSITE: www.iiicl.org*



INSTITUTE OF INTERNATIONAL CONTAINER LESSORS



*1990 M STREET NW, SUITE 650, WASHINGTON, DC 20036-3417 USA
TELEPHONE: 202 223-9800 FAX: 202 223-9810 WEBSITE: www.iicl.org*



INSTITUTE OF INTERNATIONAL CONTAINER LESSORS



*1990 M STREET NW, SUITE 650, WASHINGTON, DC 20036-3417 USA
TELEPHONE: 202 223-9800 FAX: 202 223-9810 WEBSITE: www.iiicl.org*



INSTITUTE OF INTERNATIONAL CONTAINER LESSORS



*1990 M STREET NW, SUITE 650, WASHINGTON, DC 20036-3417 USA
TELEPHONE: 202 223-9800 FAX: 202 223-9810 WEBSITE: www.iicl.org*



INSTITUTE OF INTERNATIONAL CONTAINER LESSORS



*1990 M STREET NW, SUITE 650, WASHINGTON, DC 20036-3417 USA
TELEPHONE: 202 223-9800 FAX: 202 223-9810 WEBSITE: www.iicl.org*



INSTITUTE OF INTERNATIONAL CONTAINER LESSORS



*1990 M STREET NW, SUITE 650, WASHINGTON, DC 20036-3417 USA
TELEPHONE: 202 223-9800 FAX: 202 223-9810 WEBSITE: www.iiicl.org*