



IICL FTB 001, 1 February 1, 2011

Title: “Flatrack Inspection Criteria”

Reference: Revision to “Guide for Flatrack Container Inspection”

The following is a revision to the Guide for Flatrack Container Inspection, Table 3.4 (Side Rails, End Sills, Lower Coenr Posts and Outer Hinges).

<u>Component</u>	<u>Condition</u>	<u>Action Required</u>
Side rail top flange	Any deformation such as bend, bow, dents, etc.	If more than 20mm (3/4 in) deep, REPAIR OR if more than 10mm (3/8 in) deep and Greater than 200mm (8 in) long, REPAIR

IICL FTB 001 was prepared under the supervision of the IICL Technology Committee.