



May 19, 2025

**IICL issues clarification on bottom side rails of refrigerated containers**

**Due to the variety of designs and profiles on bottom side rails and with the intent to clarify the correct component code to be used when estimating repairs, please note the picture below:**



**Please contact [technical@iicl.org](mailto:technical@iicl.org) if any questions.**

Organized in 1971, the IICL is a trade association, representing lessors of maritime containers and intermodal chassis. Its member companies, CAI International, Inc., Direct ChassisLink, FlexiVan, Seaco Global, SeaCube Container, Textainer Group Holdings Limited, TOUAX, TRAC Intermodal, and Triton International Limited, own or manage a significant portion of the global leased container and U.S. chassis fleets.

The IICL is active in technological, educational, safety, environmental, governmental, regulatory, and security issues. Complementing its widely accepted industry standards and best practices, the IICL offers its inspector certification examinations for containers and chassis in more than 5,000 locations around the world, supported by publications, tools and courses.

For more information, please contact the IICL via [info@iicl.org](mailto:info@iicl.org)