

INSTITUTE OF INTERNATIONAL CONTAINER LESSORS (IICL)

ISO CEDEX CODES

ISO 9897-5

CHASSIS

PROPOSED CEDEX CODES LIST

<u>Date</u>	<u>Component</u>	<u>Proposed Code</u>
2/23/2015	Tire Inflation System Long Hose	PLH
2/23/2015	Tire Inflation System Short Hose	PLS
2/23/2015	Tire Inflation System Control Box	PRC
2/23/2015	Tire Inflation System Valve ("T")	PTF
2/23/2015	Tire Inflation System Hub Cap	PHC
2/23/2015	Tire Inflation System State/Filter	PSF
2/23/2015	Tire Inflation System Transmit Line	PTL
2/23/2015	Tire Inflation System Control Box Bracket	PCB
2/23/2015	Tire Inflation System Protector Valve	PPV
2/23/2015	Tire Inflation System Line Filter	PLF
2/23/2015	Tire Inflation System Relief Valve Flapper	PVF
2/23/2015	Tire Inflation System Deflector Shield	PDS
2/23/2015	Tire Inflation System Indicator Light	PIL
2/23/2015	Tire Inflation System Self Draining Filter	PDF
2/23/2015	Tire Inflation System Control Box Lid	PBL
2/23/2015	Tire Inflation System Pressure Reg Valve	PRV
2/23/2015	Tire Inflation System Sensing Switch	PFS
2/23/2015	Tire Inflation System Bulkhead Check Valve	PBV
2/23/2015	Tire Inflation System Shut Off Valve	POV
2/23/2015	Tire Inflation System Flow Sensing Fitting	PFF
2/24/2015	Tire Inflation System Indicator - LED	PLE